

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-003140**Date Inspected:** 16-Jun-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 630**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1530**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai,China**CWI Name:** C. M. Chen**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

Caltrans Quality Assurance (QA) Inspector Tim McClendon arrived on site at the Zhenhua Port Machinery Company (ZPMC) facility at Changxing Island, in Shanghai, China to periodically monitor welding and Quality Control (QC) functions. While on site the QA Inspector observed and/or discovered the following.

QA Inspector, McClendon, observed the work being performed in Bay 2 of the New OBG. ZPMC personnel were performing various functions related to the fabrication of the OBG Side Plates and Bottom Plates as well as the deck sections in the jig fixture. The fabrication performed includes but is not limited to the preparation of areas where temporary welds for strongbacks are located, bevel preparation and welding of the Complete Joint Penetration welds (CJP) on Side Plates and Bottom Plates, heat straightening of Side Plates and Bottom Plates.

OBG Assembly Segment 3AE- ZPMC is in process of welding the floor beam FL2-1 (Floor Beam) to 3A-D6 (Bottom Plate). In addition, Caltrans QA observed weld repair on a Complete Joint Penetration (CJP) weld joining 3AE-C5 to 3AE-D6 for the first time.

OBG Assembly Segment 3BE- ZPMC was observed erecting temporary deck panel supports on said segment at two (2) locations.

OBG Assembly Segment 4BE- ZPMC was observed completing weld bevel joint preparation at FL1-1S to FL2-1S.

General Note: All work observed today, unless otherwise noted, appeared to generally comply with the contract

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

documents.

Summary of Conversations:

No relevant conversations spoken on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Pat Lowry, (858) 344-2712, who represents the Office of Structural Materials for your project.

Inspected By:	McClendon,Timothy
----------------------	-------------------

Quality Assurance Inspector

Reviewed By:	Cuellar,Robert
---------------------	----------------

QA Reviewer
